

## REFRACTECH THERMBOND REPAIR REPORT AT LOY YANG POWER



November 2006: Thermbond chemical bond castable precast boiler door block. Andreco cast Thermbond Formula 6L door block into timber mould.



November 2006: Thermbond Formula 6L precast door block for boiler furnace.



November 2006: Loy Yang Power Mill door Thermbond gunning repairs.  
Thermbond Formula 6AG gunning castable installed to repair fired refractory.



November 2006: Condition of Loy Yang Power mill door fired refractory **before**  
Thermbond F6AG castable gunned onto mill door fired refractory.



November 2006: Result of spraying 48 bags Thermbond Formula 6AG gunning castable onto fired, cleaned refractory in Loy Yang Power 2-PFM-5 boiler mill door.



November 2006: Contractor Andreco Hurll spraying Thermbond Formula 6AG gunnite, showing low dust emission and minimal rebound during gunning operation.



November 2006: Thermbond gunning repair operation at Loy Yang Power Mill door



November 2006: Thermbond gunning nozzle assembly for Loy Yang gunning repairs.